



Drawing

 Hendi B.V. Steenoven 21 3911 TX Rhenen The Netherlands	Batch #	Appliance part#
	000000 and up	810316
	Description	
	Washbasin knee operated	

Date	26-06-2018	Revision #	1.0
Revision	First Bill of Materials (BOM)		



Bill of materials (BOM)

 <b style="font-size: 2em; color: red;">HENDI <small>FOOD SERVICE EQUIPMENT</small> Hendi B.V. Steenoven 21 3911 TX Rhenen The Netherlands	Batch #	Appliance part#
	000000 and up	810316
	Description	
Washbasin knee operated		

Date	26-06-2018	Revision #	1.0
Revision	First Bill of Materials (BOM)		

Item	Description	Part#	Quantity	Remark	Picture
1	Knee Push Button	945506	1		
2	Push Button Valve	945445	1		
3	Screw with Plug	n/a	1	Obtain Locally	
4	Drainage Set Complete	945469	1		
5	Faucet	945513	1		
6	Flexible Hose	945483	2		
7	Sink	n/a	1		

n/a -> not available
nss -> not sold separately